

**WIND Data Download**

Retrieval Date 5/18/2012

- Location
- M1
  - M2
  - M7
  - MB
  - Other \_\_\_\_\_

CART #4 V18935

**Sontek ADV**

(upward looking)

- Sensor
- B336 (V20358) & G494 (V20364)
  - B337 (V20359) & G447 (V20365)
  - B338 (V20360) & G446 (V20366)
  - Other \_\_\_\_\_

Download Computer V18476

Filename MBM12001.a2r

Size 578.38 MB

**ADCP (RDI 600 or 1200) kHz**

- Sensor
- WHSW1200-I-UG34 (s/n 5793) (V18437)
  - WHSW600-I-UG65 (s/n 7260) (ET-0485)
  - Other \_\_\_\_\_

Download Computer V18476

Filename MBM12001.000

Size 15,007 KB

**YSI 6600 CTD**

Scully TCO

- Sensor
- 03H1988 (V17937)
  - 03K0492 (V20008)
  - 07B1391 (V20490)
  - Other \_\_\_\_\_

Download Computer \_\_\_\_\_

Filename \_\_\_\_\_

Size \_\_\_\_\_

**WIND Data Download**

**Retrieval Date** 5/18/2012

- Location**
- M1
  - M3
  - M4
  - M5
  - S2
  - Other MB

**HOBO TC**

- Sensor**
- SN 9945142
  - SN 10075264
  - SN 10075265
  - SN 10075266
  - SN 10075267
  - SN 10075268
  - SN 10075269
  - SN 10075270
  - SN 10075272
  - SN 10075273
  - SN 10075274
  - Other \_\_\_\_\_

Download Computer V18476

Filename MB-MAR12

Size 465 KB

**COMMENTS**

1st Attempt at Acoustic ~~probe~~ release failed. came back later + float was up.

buoy line wrapped around ADV sensor when retrieved. used second line to relieve pressure + remove 1st line before brought on board.

VERY ANOXIC Black MUD! looked like water settled maybe 8 inches??