

# WIND Data Download

Retrieval Date 5/18/2012

Location

- M1
- M2
- M7
- MB
- Other \_\_\_\_\_

CART # 2

## Sontek ADV

(UPWARD Looking)

Sensor

- B336 (V20358) & G494 (V20364)
- B337 (V20359) & G447 (V20365)
- B338 (V20360) & G446 (V20366)
- Other \_\_\_\_\_

Download Computer

V R476

Filename

MIM12000.qdr

Size

58.38 MB

## ADCP (RDI 600 or 1200) kHz

Sensor

- WHSW1200-I-UG34 (s/n 5793) (V18437)
- WHSW600-I-UG65 (s/n 7260) (ET-0485)
- Other \_\_\_\_\_

Download Computer

V18476

Filename

MIM12000.000

Size

12,359 KB

## YSI 6600 CTD

Sensor

- 03H1988 (V17937)
- 03K0492 (V??008)
- 07B1391 (V20490)
- Other \_\_\_\_\_

Download Computer \_\_\_\_\_

Filename \_\_\_\_\_

Size \_\_\_\_\_

**WIND Data Download**

**Retrieval Date** 5/18/12

**Location**

- M1
- M3
- M4
- M5
- S2
- Other \_\_\_\_\_

**HOBO TC**

**Sensor**

- SN 9945142
- SN 10075264
- SN 10075265
- SN 10075266
- SN 10075267
- SN 10075268
- SN 10075269
- SN 10075270
- SN 10075272
- SN 10075273
- SN 10075274
- Other \_\_\_\_\_

Download Computer V18476

Filename M1 - MAX 12

Size 42,368 KB

**COMMENTS**

TriLux 33 paint on ADCP + ADV  
Failed - Barnicle growth on sensors. Hobo sensor  
clear. Frame clear.